

List of Current AD's Shown at the FAA Website effective 26th August 2006.

AA1 - Yankee

85-21-02	10/28/1985	Seat Belt Attachment Bracket
78-13-04	06/30/1978	Fuel Measurement Gauge
76-17-03	08/30/1976	Delaminations in Bonded Skin
75-09-07	04/25/1975	Mixture Control Wires
75-07-04	Upon Receipt	Rudder Control Bar Assemblies
73-13-07	06/25/1973	Placard Installation
72-07-10	07/10/1974	Wear on Elevator Bungee Housing
72-06-02	08/29/1974	Rudder Aileron and Elevator Control Cables
71-04-03	02/25/1971	Nose Gear Strut
70-25-05	12/08/1970	Bungee Mounting Plate
70-05-05	03/13/1970	Muffler Inspection

AA1A

85-21-02	10/28/1985	Seat Belt Attachment Bracket
78-13-04	06/30/1978	Fuel Measurement Gauge
76-17-03	08/30/1976	Delaminations in Bonded Skin
75-09-07	04/25/1975	Mixture Control Wires
75-07-04	Upon Receipt	Rudder Control Bar Assemblies
73-13-07	06/25/1973	Placard Installation
72-07-10	07/10/1974	Wear on Elevator Bungee Housing
72-06-02	08/29/1974	Rudder Aileron and Elevator Control Cables

AA1B - Trainer

85-21-02	10/28/1985	Seat Belt Attachment Bracket
78-13-04	06/30/1978	Fuel Measurement Gauge
76-17-03	08/30/1976	Delaminations in Bonded Skin
75-09-07	04/25/1975	Mixture Control Wires
75-07-04	Upon Receipt	Rudder Control Bar Assemblies
73-13-07	06/25/1973	Placard Installation
72-07-10	07/10/1974	Wear on Elevator Bungee Housing
72-06-02	08/29/1974	Rudder Aileron and Elevator Control Cables

AA1C – T/Cat - Lynx

85-21-02	10/28/1985	Seat Belt Attachment Bracket
--------------------------	------------	------------------------------

AA5 - Traveller

89-18-08	09/21/1989	Fuel Tank/Fuel System
81-24-03	11/16/1981	Engine Power Loss Prevention
79-22-04	11/09/1979	Aileron System
77-07-04	04/11/1977	Carburetor Heat Valve Assembly
76-17-03	08/30/1976	Delaminations in Bonded Skin
76-01-02	02/25/1976	Engine Cowl
75-07-04	Upon Receipt	Rudder Control Bar Assemblies
72-06-02	08/29/1974	Rudder Aileron and Elevator Control Cables
95-19-15 R1	10/03/2005	Wing attach shoulder bolts

AA5A - Cheetah

89-18-08	09/21/1989	Fuel Tank/Fuel System
81-24-03	11/16/1981	Engine Power Loss Prevention
79-22-04	11/09/1979	Aileron System
77-08-03	04/19/1977	Static System
77-07-04	04/11/1977	Carburetor Heat Valve Assembly
76-22-09	11/10/1976	Oil Coolers
76-17-03	08/30/1976	Delaminations in Bonded Skin
76-01-02	02/25/1976	Engine Cowl
95-19-15 R1	10/03/2005	Wing attach shoulder bolts

AA5B - Tiger

89-18-08	09/21/1989	Fuel Tank/Fuel System
81-24-03	11/16/1981	Engine Power Loss Prevention
79-22-04	11/09/1979	Aileron System
77-08-03	04/19/1977	Static System
76-22-09	11/10/1976	Oil Coolers
76-17-03	08/30/1976	Delaminations in Bonded Skin
76-04-05	02/25/1976	Carburetor Mixture Control Wire
76-01-02	02/25/1976	Engine Cowl
75-07-04	Upon Receipt	Rudder Control Bar Assemblies
95-19-15 R1	10/03/2005	Wing attach shoulder bolts